

BMIC Brownfields Public Record

Site Name	Site Size	Analysis of Brownfields Cumulative Alternatives (ABCA)	Actions Taken	Institutional Control	Nature of Contamination	Reports	Final Clean Up Report
Silver Dome	0.10 Acre	Silver Dome ABCA	Soil removal Ongoing monitoring	Restrictive Covenant	Soil Ground Water	Remediation Excavation Report Ground Water Investigation and Risk Assessment Subsurface Investigation	Pending
Chippewa Landing	3 Acres	Pending	Seeking funds for clean up of site	Site Security - No Trespassing Signage	Soil	N/A	N/A

Updated 10/2021